

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information																			
Last Name			First Name			License #			State										
BECERRA			JOSE			B260436684230			FL										
Crash Activity																			
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)																			
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0					
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0					
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)																			
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries							
Inspection Activity (3 year history from MCMIS snapshot date)																			
Inspection Summary																			
Driver Summary				Vehicle Summary				Hazmat Summary											
Driver Inspections:				5				Vehicle Inspections:				4				Hazmat Inspections		1	
Driver Out-of-service Inspections:				1				Vehicle Out-of-service Inspections:				2				Hazmat Out-of-service Inspections:		0	
Driver Out-of-service Rate:				20%				Vehicle Out-of-service Rate:				50%				Hazmat Out-of-service Rate:		0%	
Inspection Details																			
Carrier Info				Driver Info				Inspection Info											
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol							
1	11/10/2021	789300	BECERRA'S TRANSPORT CORP	BECERRA, JOSE	B260436684230	FL	11/23/1968	FL	2703001298	Y	3	0							

Report executed at: 5/13/2024 3:58:26 PM

MCMIS snapshot date: 04/26/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

2	03/02/2022	789300	BECERRA'S TRANSPORT CORP	BECERRA, JOSE	B260436684230	FL	11/23/1968	TX	68WA0XCMB5	N	1	15
	Vehicle Violation:	393.78		Wipers - Inoperative / missing / damaged wipers.								
	Vehicle Violation:	396.17(c)		Operating a CMV without proof of a periodic inspection								
	Vehicle Violation:	393.9(a)		Inoperative turn signal								
	Vehicle Violation:	393.19		Inoperative/Defective Hazard Warning Lamp								
	Vehicle Violation:	393.9(a)		Inoperable head lamps								
	Vehicle Violation:	396.3(a)(1)		Brake system pressure loss							OOS	
	Vehicle Violation:	393.45(d)		Brake Connections with Leaks - Connection to Power Unit								NON-OOS
	Vehicle Violation:	396.3(a)(1)		Inspection, repair and maintenance of parts and accessories								NON-OOS
	Vehicle Violation:	393.95(a)		No/discharged/unsecured fire extinguisher								NON-OOS
	Vehicle Violation:	393.207(b)		Adjustable axle locking pins missing or not engaged								NON-OOS
	Vehicle Violation:	396.17(c)		Operating a CMV without proof of a periodic inspection								NON-OOS
	Vehicle Violation:	396.5(b)		Hubs - Oil and/or Grease Leaking from hub - inner wheel								OOS
	Vehicle Violation:	393.47(e)		Brake Out of Adjustment - Roto, Clamp (Short & Long), DD-3, or Bolt								NON-OOS
	Vehicle Violation:	393.47(e)		Brake Out of Adjustment - Roto, Clamp (Short & Long), DD-3, or Bolt								NON-OOS
	Vehicle Violation:	393.53(b)		CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear								NON-OOS
3	05/02/2022	2102795	MLD GROUP INC	BECERRA, JOSE	B260436684230	FL	11/23/1968	MS	6612090927	N	2	2
	Vehicle Violation:	396.17(c)		Operating a CMV without proof of a periodic inspection								NON-OOS
	Vehicle Violation:	393.9(a)		Inoperable Required Lamp								NON-OOS
4	11/26/2022	3748814	MGM QUALITY CARRIERS LLC	BECERRA, JOSE	B260436684230	FL	11/23/1968	FL	4126000314	N	2	4
	Vehicle Violation:	393.9(a)		Inoperative turn signal								NON-OOS
	Vehicle Violation:	393.75(a)(3)		Tire-flat and/or audible air leak								OOS
	Driver Violation:	395.22(h)(4)		Driver failed to maintain supply of blank drivers records of duty status graph-grids								NON-OOS
	Driver Violation:	395.8(a)(1)		ELD - No record of duty status (ELD Required)								OOS
5	03/09/2023	2280884	ORBITZ SERVICES & SUPPLIES LLC	BECERRA, JOSE	B260436684230	FL	11/23/1968	TX	6J8D0XUT6Y	N	2	1
	Vehicle Violation:	393.30		Improper battery installation								NON-OOS

Report executed at: 5/13/2024 3:58:26 PM

MCMIS snapshot date: 04/26/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

Violation Summary			
Violation #	Description	# of Violations	# of Out-of-service Violations
396.17(c)	Operating a CMV without proof of a periodic inspection	3	0
393.9(a)	Inoperable Required Lamp	4	0
393.30	Improper battery installation	1	0
393.78	Wipers - Inoperative / missing / damaged wipers.	1	0
393.19	Inoperative/Defective Hazard Warning Lamp	1	0
396.3(a)(1)	Brake system pressure loss	2	1
393.45(d)	Brake Connections with Leaks - Connection to Power Unit	1	0
393.95(a)	No/discharged/unsecured fire extinguisher	1	0
393.207(b)	Adjustable axle locking pins missing or not engaged	1	0
396.5(b)	Hubs - Oil and/or Grease Leaking from hub - inner wheel	1	1
393.47(e)	Brake Out of Adjustment - Roto, Clamp (Short & Long), DD-3, or Bolt	2	0
393.53(b)	CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear	1	0
393.75(a)(3)	Tire-flat and/or audible air leak	1	1
395.22(h)(4)	Driver failed to maintain supply of blank drivers records of duty status graph-grids	1	0
395.8(a)(1)	ELD - No record of duty status (ELD Required)	1	1

The summary counts and rates only include violations that were attributable to BECERRA, JOSE.

Report executed at: 5/13/2024 3:58:26 PM

MCMIS snapshot date: 04/26/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>