

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #			State								
EFTEKHARI		EFTEKHARI		40161490			TX								
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		1		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		1		# of Towaways:		1	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		1		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
1	02/13/2022	3696955		MOHAMMAD, EFTEKHARI	40161490	TX	08/23/1988	CA	CA39050-4982	INDUSTRIAL DR/880ft W of B ST	0	1			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		4		Vehicle Inspections:		3		Hazmat Inspections				0			
Driver Out-of-service Inspections:		1		Vehicle Out-of-service Inspections:		1		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		25%		Vehicle Out-of-service Rate:		33%		Hazmat Out-of-service Rate:				0%			

Report executed at: 8/27/2024 1:07:10 PM

MCMIS snapshot date: 07/26/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	10/05/2021	3696955	ARYO EXPRESS LLC	EFTEKHARI, MOHAMMAD	40161490	TX	08/23/1988	NM	7749L7Q4MH	N	2	4
Vehicle Violation: 393.9(a) Inoperable Required Lamp NON-OOS Vehicle Violation: 393.11 Truck-Tractor upper body corner requirements for retroreflective sheeting or reflex reflective material for vehicles manufactured after July 1997 NON-OOS Vehicle Violation: 393.9(a) Inoperable Required Lamp NON-OOS Vehicle Violation: 390.21(b) Carrier name and/or USDOT Number not displayed as required NON-OOS												
2	11/18/2021	3696955	ARYO EXPRESS LLC	MOHAMMED, EFTEKHARI	40161490	TX	08/23/1988	FL	3099006816	N	2	4
Driver Violation: 395.8(e)(1) False report of drivers record of duty status OOS Vehicle Violation: 393.9(a) Inoperative turn signal NON-OOS Vehicle Violation: 393.9(a) Inoperable Required Lamp NON-OOS Vehicle Violation: 393.75(a)(3) Tire-flat and/or audible air leak OOS												
3	05/26/2023	2946610	WFT LOGISTICS INC	EFTEKHARI, MOHAMMAD	40161490	TX	08/23/1988	AZ	0307002832	N	2	3
Driver Violation: 392.82(a)(1) Using a hand-held mobile telephone while operating a CMV NON-OOS Vehicle Violation: 393.95(a) No/discharged/unsecured fire extinguisher NON-OOS Vehicle Violation: 393.67(c)(7)(v) Fuel tank fill pipe cap missing NON-OOS												
4	11/30/2023	3602135	BRABUS TRANSPORT INC	EFTEKHARI, MOHAMMAD	40161490	TX	08/23/1988	NY	SPWD111538	N	3	1
Driver Violation: 395.24(c)(2)(iii) Driver failed to manually add shipping document number NON-OOS												
Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
392.82(a)(1)	Using a hand-held mobile telephone while operating a CMV								1	0		
393.95(a)	No/discharged/unsecured fire extinguisher								1	0		
393.67(c)(7)(v)	Fuel tank fill pipe cap missing								1	0		
393.9(a)	Inoperable Required Lamp								4	0		
393.11	Truck-Tractor upper body corner requirements for retroreflective sheeting or reflex reflective material for vehicles manufactured after July 1997								1	0		
390.21(b)	Carrier name and/or USDOT Number not displayed as required								1	0		
395.24(c)(2)(iii)	Driver failed to manually add shipping document number								1	0		

Report executed at: 8/27/2024 1:07:10 PM

MCMIS snapshot date: 07/26/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

395.8(e)(1)	False report of drivers record of duty status	1	1
393.75(a)(3)	Tire-flat and/or audible air leak	1	1

The summary counts and rates only include violations that were attributable to EFTEKHARI, EFTEKHARI.

Report executed at: 8/27/2024 1:07:10 PM

MCMIS snapshot date: 07/26/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.