

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name			License #				State					
THORNE	MARK			T650585051270				MI					
Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:		0	# of Crashes with Fatalities:		0	# of Crashes with Injuries:		0	# of Towaways:		0		
# Not preventable:		0	# of Fatalities:		0	# of Injuries:		0	# of Hazmat Releases:		0		
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	
Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		4	Vehicle Inspections:		2	Hazmat Inspections				0			
Driver Out-of-service Inspections:		0	Vehicle Out-of-service Inspections:		1	Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		0%	Vehicle Out-of-service Rate:		50%	Hazmat Out-of-service Rate:				0%			

Report executed at: 6/29/2022 2:03:21 PM

MCMIS snapshot date: 05/27/2022

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	09/18/2019	247552	TRADITION TRANSPORTATION CO LLC	THORNE, MARK	T650585051270	MI	04/06/1978	TX	5K0F0XNG57	N	1	7
Vehicle Violation: 393.9(a) Inoperable tail lamp NON-OOS Vehicle Violation: 393.55(d)(2) CMV manufactured on/after 3/1/2001 not equipped with ABS malfunction circuit / lamp from towed vehicle in cab. NON-OOS Vehicle Violation: 393.55(e) No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998 NON-OOS Vehicle Violation: 393.75C Tire-other tread depth less than 2/32 of inch measured in a major tread groove NON-OOS Vehicle Violation: 393.75C Tire-other tread depth less than 2/32 of inch measured in a major tread groove NON-OOS Vehicle Violation: 393.45(b)(2) Brake hose or tubing chafing and/or kinking NON-OOS Vehicle Violation: 396.3(a)(1) Brakes (general) Explain: NON-OOS												
2	06/13/2020	1519496	BULL LATHROM & SONS TRUCKING INC	THORNE, MARK	T650585051270	MI	04/06/1978	MO	W170000584	N	3	0
3	04/15/2021	1519496	BULL LATHROM & SONS TRUCKING INC	THORNE, MARK	T650585051270	MI	04/06/1978	IL	4038360276	N	3	0
4	05/06/2021	1519496	BULL LATHROM & SONS TRUCKING INC	THORNE, MARK	T650585051270	MI	04/06/1978	AL	JBXV001122	N	1	1
Vehicle Violation: 393.75(a)(3) Tire-flat and/or audible air leak OOS												
Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
393.9(a)	Inoperable tail lamp								1	0		
393.55(d)(2)	CMV manufactured on/after 3/1/2001 not equipped with ABS malfunction circuit / lamp from towed vehicle in cab.								1	0		
393.55(e)	No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998								1	0		
393.75C	Tire-other tread depth less than 2/32 of inch measured in a major tread groove								2	0		
393.45(b)(2)	Brake hose or tubing chafing and/or kinking								1	0		
396.3(a)(1)	Brakes (general) Explain:								1	0		

Report executed at: 6/29/2022 2:03:21 PM

MCMIS snapshot date: 05/27/2022

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

393.75(a)(3)	Tire-flat and/or audible air leak	1	1
--------------	-----------------------------------	---	---

The summary counts and rates only include violations that were attributable to THORNE, MARK.

Report executed at: 6/29/2022 2:03:21 PM

MCMIS snapshot date: 05/27/2022

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.