

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information												
Last Name	First Name	License #	State									
JOANMANUELSANCHEZ	JOANMANUEL	C262493743281	FL									
JOANCACHORROSANCHEZ	JOANMANUEL	C262493743281	FL									
CACHORROSANCHEZ	JOAN	C262493743281	FL									
JOANSANCHEZ	JOANMANUEL	C262493743281	FL									
Crash Activity												
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)												
# of Crashes:	0	# of Crashes with Fatalities:	0	# of Crashes with Injuries:	0	# of Towaways:	0					
# Not preventable:	0	# of Fatalities:	0	# of Injuries:	0	# of Hazmat Releases:	0					
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)												
Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# Injuries	
Inspection Activity (3 year history from MCMIS snapshot date)												
Inspection Summary												
Driver Summary			Vehicle Summary				Hazmat Summary					
Driver Inspections:	5		Vehicle Inspections:	3			Hazmat Inspections:			0		
Driver Out-of-service Inspections:	1		Vehicle Out-of-service Inspections:	2			Hazmat Out-of-service Inspections:			0		
Driver Out-of-service Rate:	20%		Vehicle Out-of-service Rate:	67%			Hazmat Out-of-service Rate:			0%		

Report executed at: 6/3/2022 9:32:40 AM

MCMIS snapshot date: 05/27/2022

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	12/25/2019	1725959	OMMA TRUCKING INC	CACHORRO, JOAN	C262493743281	FL	09/08/1974	TX	5MQE0MPL0Q	N	2	3
Vehicle Violation: 393.110(d) Large or odd-shaped cargo not adequately secured OOS Vehicle Violation: 393.9(a) Inoperable Required Lamp NON-OOS Driver Violation: 383.23(a)(2) Operating a CMV without a CDL OOS												
2	07/14/2020	2338965	USA LOGISTICS INC FL	CACHORRO SANCHEZ, JOAN	C262493743281	FL	09/08/1974	GA	0145003632	N	3	3
Driver Violation: 392.2 Failure to obey traffic control device NON-OOS Driver Violation: 395.15(g)(2) Driver failed to have on-board a CMV a sufficient supply of blank records of duty status graph-grids. NON-OOS Driver Violation: 392.16(a) Failing to use seat belt while operating a CMV NON-OOS												
3	04/15/2021	2828543	ZIGI FREIGHT INC	CACHORRO SANCHEZ, JOAN	C262493743281	FL	09/08/1974	GA	1224003626	N	3	1
Driver Violation: 392.82(a)(1) Using a hand-held mobile telephone while operating a CMV NON-OOS												
4	05/05/2021	2828543	ROYAL3 INC	CACHORRO SANCHEZ, JOAN	C262493743281	FL	09/08/1974	MO	H4S6004034	N	2	1
Vehicle Violation: 393.75(a)(3) Tire-flat and/or audible air leak OOS												
5	11/09/2021	2975772	ROYAL REGAL INC	CACHORRO SANCHEZ, JOAN	C262493743281	FL	09/08/1974	TN	TCGP004595	N	1	0

Violation Summary			
Violation #	Description	# of Violations	# of Out-of-service Violations
392.82(a)(1)	Using a hand-held mobile telephone while operating a CMV	1	0
393.75(a)(3)	Tire-flat and/or audible air leak	1	1
393.110(d)	Large or odd-shaped cargo not adequately secured	1	1
393.9(a)	Inoperable Required Lamp	1	0
383.23(a)(2)	Operating a CMV without a CDL	1	1
392.2	Failure to obey traffic control device	1	0
395.15(g)(2)	Driver failed to have on-board a CMV a sufficient supply of blank records of duty status graph-grids.	1	0
392.16(a)	Failing to use seat belt while operating a CMV	1	0

The summary counts and rates only include violations that were attributable to JOANMANUELSANCHEZ, JOANMANUEL.

Report executed at: 6/3/2022 9:32:40 AM

MCMIS snapshot date: 05/27/2022

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>