PSP Detailed Report

Federal Motor Carrier Safety Administration

_																		
						Driv	er Inf	form	ation									
Last Name First Name					License #						State							
COHEN NIMROD					C500620804030						FL							
						Cı	ash A	Acti	vity									
Cra	Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)																	
# of Crashes:					# of Crashes with Fatalit					# of Crashes with			0	# of To			1	
# Not preventable: 0				0		# of Fata	lities:	0				# of I	njuries:	0	# of Hazmat R			0
Cra	Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)																	
	Date	DOT#	Carrier Name		Name Driver Name			Driver Lic S		State	Driver DOB	Rpt St	Report Number		r Location	# Fatalities	# of Inj	juries
1	08/18/2023	3965830	ALJ LOG	ISTI	CS LLC	COHEN, NIMROD	C50	C500620804030		FL	11/03/1980	NC	NC0107451347		95	0	0	
	Inspection Activity (3 year history from MCMIS snapshot date)																	
Insp	ection Sumi	mary																
Driver Summary						Vehicle Summary					Hazmat Summary							
Driver Inspections: 1					Vehicle Inspections:					1 H	Hazmat Inspections 0							
Driver Out-of-service Inspections: 0					Vehicle Out-of-service Inspections:					1 H	Hazmat Out-of-service Inspections:							
Driver Out-of-service Rate:					0%	Vehicle Out-of-service Rate:					100% I	Hazmat Out-of-service Rate: 0%						0%

Report executed at: 8/30/2024 3:48:29 PM

MCMIS snapshot date: 07/26/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Carrier Info				Driver Info	Driver Info					Inspection Info					
	Date DC		Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol			
1	07/16/2024	3539046	NO1 LOGISTICS LL	C COHEN, NIMROD	C500620804030	FL	11/03/1980	NY	SPB0372904	N	2	4			
	Vehicle V	iolation:	393.11		k-Tractor upper body corner requirements for retroreflective eting or reflex reflective material for vehicles manufactured after NON-OOS 1997										
Vehicle Violation:		iolation:	393.11	Truck-Tractor lower rear mud flaps retroreflective reflective material requirements for vehicles mar 1997	ck-Tractor lower rear mud flaps retroreflective sheeting / reflex ective material requirements for vehicles manufactured after July 77			NON-OOS							
Vehicle Violation:		iolation:	393.75(a)(3)	Tire-flat and/or audible air leak			oos								
	Vehicle V	iolation:	393.9(a)	Inoperable Required Lamp			oos								
'iolati	on Summary														
Violation #				# of Violati	ons	# of Out-of-service Violations									
393.11 Tru		Tarrella Tarrella		ements for retroreflective sheeting or reflex reflec	4i			1007							

The summary counts and rates only include violations that were attributable to COHEN, NIMROD.

Tire-flat and/or audible air leak

Inoperable Required Lamp

Report executed at: 8/30/2024 3:48:29 PM

MCMIS snapshot date: 07/26/2024

393.75(a)(3)

393.9(a)

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.